

# Snowplow issue

## Damaged fixture




Asset: +RW Y3.INT.WD=TCL009  
Asset Area: TCL (RW Y3)  
Asset Type: bGG\_i

Reported By: ARN Technician  
Reported Date: Feb 22, 2021, 3:25:53 PM  
Severity: Critical

State: Resolved

Resolved By: Technician  
Resolved Date: February 22, 2021 at 3:25:53 PM GMT+1  
Last Changed By: [ALIS Support]  
Last Changed: Dec 1, 2021, 11:25:42 AM  
Attachments: 3



Imagery ©2021, CNES / Airbus, Lantmäteriet/Metria, Maxar Technologies

2/22/21



ARN Technician



3:25 PM

12/1/21

You

This is due to snowplow ; need for a snowplow ring

11:20 AM

You

Like this one

11:23 AM

You



11:23 AM

You

Like this one



11:23 AM 

11:25 AM  You changed category from 'Migrated Observation' to 'Damaged fixture'

11:25 AM  You changed title from 'Photo Observation' to 'Snowplow issue'

11:25 AM  You changed state from 'Closed' to 'Resolved'